





MAY 1, 1981 LOOKING SOUTH
TOWARD BISCEGLIA PROPERTY
AT BACK OF ERS



MAY 1, 1981 LOOKING SOUTH FROM E. END OF BLDG

COLOR PHOTOS
IN NPDES FILE


10300688



MAY 1, 1981 STILLS, EAST END OF BLDG




DRAINAGE DITCH RUNNING
EAST FROM BACK OF ERS




MAY 1, 1981

→
EXPLODED
TANK


DRAINAGE DITCH AT EAST END OF
BUILDING SHOWING DRAIN PIPE



MAY 1, 1981 FROM DAVIS PROPERTY
VIEWING SOUTH TOWARD ERS




MAY 1, 1981 FROM DAVIS PROPERTY
VIEWING SW TOWARD ERS




MAY 1, 1981

DITCH AT NE CORNER OF Building



MAY 1, 1981


LOOKING NE TOWARD DAVIS
PROPERTY FROM ERS




← DAVIS PROPERTY AT NE
CORNER OF BLDG.




JUNE 20, 1978
10" PIPE WITH OIL STAINED
GRASS IN FRONT OF ERS



JUNE 30, 1978
DEAD VEGETATION IN REAR OF GRIFFIN HOUSE
AND ALONG FENCE DRAINAGE DITCH



DRAINAGE DITCH ON NORTH SIDE OF
BUILDING. DITCH DRAINS WEST




5/1/81


GARDEN PLOT IMMEDIATELY BEHIND BLDG.

PROXIMITY OF DAVIS GROUNDWATER
WELL TO ERS FACILITY

MAY 1, 1981




MAY 1, 1981 STORAGE AREA




MAY 1, 1981 EMPTY DRUM STORAGE




MAY 1, 1981
TANK WHICH BLEW UP (ON RIGHT)



MAY 1, 1981 CLEAN MATERIAL STORAGE
FRONT OF BLDG. SOUTH SIDE



MAY 1, 1981 DRAINAGE DITCH AT EAST
END OF BUILDING. TOP OF TANK WHICH
EXPLODED AT RIGHT FOREGROUND.
DITCH APPROX. 120' X 3 1/2' ~~000000~~
INSIDE FENCE, SAME SIZE OUTSIDE FENCE
BEFORE ENTERING STATE WATERS



② 10:24 AM 1/20/34 Eng. Dept. Systems


Jean K. Shulds



② 10:24 AM


1/20/34

Jean K. Shulds



③ 10:29 AM Eng. Dept. Systems

1/20/34 Jean K. Shulds



③ 10:30 AM Eng. Dept. Systems

1/20/34 Jean K. Shulds